

Log Entry #C25-92

2025-01-07 13:47

2025-01-07 13:47

ETB requests FDR 20-9 (ETB misspoke, meant to say 29-9) de-energized due to proximity to fire

1349: ETB corrected request, ETB requests FDR 29-9 de-energized, urgent, non-emergency

1424: ECC advised ETB no ETA for operator to DS-29

1510: ACO reports no access to DS-29 due to fire.

1534: ECC advised ETB no access for operator to DS-29 and RTU for DS-29 is out of scan

1803: SSO arrived to DS-29

1805: ECC advised ETB operator in at DS-29, ETB reports no circuits need to be de-energized at this time.

1807: DS-29 reports SSO will need to evacuate DS-29 soon

1807: ECC advised ETB operator at DS-29 will need to evacuate soon.



Ochoa (Electric Trouble Board)

Kyi (ACO)

Montelongo (29)

2025-01-07 18:10

ETB requests FDR 29-8 de-energized

1811: SSO instructed to de-energize 29-8, SSO reports he will perform required switching but will need to evacuate DS-29 immediately after completing switching



Ochoa (Electric Trouble Board)

2025-01-07 18:18

DS-29 reports

Remote cord B/O, unable to de-energize 29-8, fire is outside DS-29 and SSO needs to evacuate

1819: ECC advised ETB SSO needed to evacuate DS-29, no circuits were de-energized



Montelongo (29)

Ochoa (Boa)

2025-01-07 23:24

Log Entry Closed.

2025-01-29 16:06

Gonzalo Mendoza changed the Log Entry Time from 2025-01-07 18:18 PST to 2025-01-07 13:47 PST